



To Be Scanned

BU15-00504

City of Corvallis, Oregon  
Development Services Division  
501 SW Madison Avenue, PO Box 1083  
Corvallis, OR 97339-1083  
541-766-6929  
[development.services@corvallisoregon.gov](mailto:development.services@corvallisoregon.gov)

## MOISTURE-SENSITIVE WOOD FRAMING MOISTURE CONTENT

Permit No.: BU15-00504

Site Address: 1545 N.W. 29th St.

Subdivision/Lot: \_\_\_\_\_

and/or

Map And Tax Lot: \_\_\_\_\_

To conform with the 2011 Oregon Residential Specialty Code (ORSC), Section R318.2 and OAR 918-480-0140, I am notifying the building official that I am aware of the moisture content requirement of ORSC Section R318.2 and have taken steps to meet this code requirement. [Section R318.2 is provided for reference.]<sup>1</sup>

Signed: Kyle Nelson Date: 10-14-2015  
Owner/General Contractor/Authorized Agent

Print Name: Kyle Nelson Kyle Nelson

<sup>1</sup> ORSC Section R318.2. Moisture Control. Prior to the installation of interior finishes\*, the building official shall be notified in writing by the general contractor that all moisture-sensitive wood framing members used in construction have a moisture content of not more than 19 percent of the weight of dry wood framing members.

\* [Moisture content verification form must be provided prior to, or at the time of requesting the insulation inspection.]